

Cordless Cooler & Warmer Box CW001G







 $-18^{\text{cool}} \sim 60^{\text{Warm}} [0 \sim 140 \sim 1$



Large capacity

20 L

IPX4



Powered

Compatible with 4 power sources













Work amount on full battery charge

-18°C [0°F] about

10 h

5°C [40°F] about

28 h

60°C [140°F] about

about

8.5 h

With two BL4050F batteries



by 40Vmax XGT Li-Ion battery









Caulk tubes to be warmed must be brand new and unopened.

Also caulk tubes must be stored in the box within the storage temperature range recommended by the manufacturer of caulk tubes.*

*Do not store opened caulk tubes with foods because they produce volatile gas.





More detailed inside temperature settings

	Cool storage							Hot storage						
°C	-18	-15	-10	-5	0	5	10	30	35	40	45	50	55	60
°F	0	5	15	25	30	40	50	85	95	105	115	120	130	140

Indication lamps

- Cooling lamp or Warming lamp indicates whether the machine is cooling or warming.
- Power lamp turns on when the machine is powered by external source (from cigar socket or AC socket through AC adapter).

Cooling lamp

makita.

Warming lamp



20 L (5.3gal) IPX4-rated capacity water resistance USB output port





