

Uni-Lock Lever-Action Protective Caps, Panel Mounts & 45° Mounts



Pro caps with Stainless Steel Turn Buckles, ADD SSTB to the part number indicated

Protective Caps		Panel Mounts		Panel Mount Shells		Panel Mount Inserts		45° Mount
Male	Female	Male	Female	Male	Female	Male	Female	
3 Power and 1 Ground with single pilot contact								
3325656-201	3325656-101	8343-1601	8343-1201	A-324289LA	324088LA	8343-601	8343-101	4543
3325656-401	3325656-301	8344-201	8344-101	A-324063LA	324063LA	8344-1601	8344-1501	4544
3325656-601	3325656-501	8345-1501	8345-1001	A-324119LA	324093LA	8345-201	8345-101	4545
3325656-801	3325656-701	8346-1301	8346-801	A-324232LA	324059LA	8346-1601	8346-1501	4546
3325656-1001	3325656-901	8347-1301	8347-801	A-324166LA	324094LA	8347-1601	8347-1501	N/A
3325656-1201	3325656-1101	8348-1001	8348-201	324095LA	324065LA	8348-401	8348-501	N/A
3 Power and 1 Ground with 2 pilot contacts								
3325656-201	3325656-101	8343-1602	8343-1202	A-324289LA	324088LA	8343-602	8343-102	4543
3325656-401	3325656-301	8344-202	8344-102	A-324063LA	324063LA	8344-1602	8344-1502	4544
3325656-601	3325656-501	8345-1502	8345-1002	A-324119LA	324093LA	8345-202	8345-1012	4545
3325656-801	3325656-701	8346-1302	8346-802	A-324232LA	324059LA	8346-1602	8346-1502	4546
3325656-1001	3325656-901	8347-1306	8347-802	A-324166LA	324094LA	8347-1602	8347-1502	N/A
3325656-1201	3325656-1101	8348-1002	8348-202	324095LA	324065LA	8348-402	8348-502	N/A
3 Power and 1 Ground with 3 pilot contacts								
3325656-201	3325656-101	8343-1603	8343-1203	A-324289LA	324088LA	8343-603	8343-103	4543
3325656-401	3325656-301	8344-203	8344-103	A-324063LA	324063LA	8344-1603	8344-1503	4544
3325656-601	3325656-501	8345-1503	8345-1003	A-324119LA	324093LA	8345-203	8345-103	4545
3325656-801	3325656-701	8346-1303	8346-803	A-324232LA	324059LA	8346-1603	8346-1503	4546
3325656-1001	3325656-901	8347-1303	8347-803	A-324166LA	324094LA	8347-1603	8347-1503	N/A
3325656-1201	3325656-1101	8348-1003	8348-203	324095LA	324065LA	8348-403	8348-503	N/A

These are connector ratings only.

Operating ratings must be based on cable capacity.