

Control Power Transformers³

| Device | Primary Voltage | Secondary Voltage | Frame Size | Catalogue Number |
|---|-----------------|-------------------|------------|------------------|
| 45 VA Control Transformer, 1-Secondary Fuse | 208 | 120 | S00 | KTH050 |
| 45 VA Control Transformer, 1-Secondary Fuse | 240/480 | 120 | S00 | KT8050 |
| 45 VA Control Transformer, 1-Secondary Fuse | 600 | 120 | S00 | KT9050 |
| 75 VA Control Transformer, 2-Primary and 1-Secondary Fuse | 208 | 120 | S0 | KTH075 |
| 75 VA Control Transformer, 2-Primary and 1-Secondary Fuse | 240/480 | 120 | S0 | KT8075 |
| 75 VA Control Transformer, 2-Primary and 1-Secondary Fuse | 600 | 120 | S0 | KT9075 |

| Device | Catalogue Number | |
|--|------------------|---------------|
| | Frame Size S00 | Frame Size S0 |
| 1 NO + 1 NC laterally mounted, screw terminals | 3RH2911-1DA11 | 3RH2921-1DA11 |
| 2 NO laterally mounted, screw terminals | – | 3RH2921-1DA20 |
| 2 NC laterally mounted, screw terminals | 3RH2911-1DA02 | 3RH2921-1DA02 |



For more accessories please refer to catalogue:
[siemens.com/ca/en/products/automation/industrial-controls.html](https://www.siemens.com/ca/en/products/automation/industrial-controls.html)

³ Large size enclosure required