




MARKER REMOVAL INSTRUCTIONS



FOLD AT UPPER PERFORATION




CREASE PERFOATION




FOLD & CREASE LOWER PERFORATION

PANDUIT © B20391, REV. 0


MARKER REMOVAL INSTRUCTIONS



FOLD AT UPPER PERFORATION




CREASE PERFOATION




FOLD & CREASE LOWER PERFORATION

PANDUIT © B20391, REV. 0


MARKER REMOVAL INSTRUCTIONS



FOLD AT UPPER PERFORATION



CREASE PERFOATION



FOLD & CREASE LOWER PERFORATION

PANDUIT © B20391, REV. 0